

**Archived:** Tuesday, June 14, 2016 11:55:56 AM

**From:** Jason P Ericson (Services - 6)

**Sent:** Monday, June 06, 2016 5:46:50 PM

**To:** Glassman, Joseph (DEQ)

**Cc:** Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)

**Subject:** Crystal Substation and Roaches Run Weekly Update: June 6, 2016

**Importance:** Normal

---

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point.

If you have any questions please contact John Black or me.

Thank you,  
Jason

Jason P. Ericson, PG  
Dominion Resources Services, Inc.  
Environmental Policy  
5000 Dominion Blvd  
Glen Allen, VA 23060  
Phone: (804) 273-3012  
Mobile: (804) 317-9464  
Fax: (804) 273-2964

**Crystal Substation Daily  
Inspection Notes and Summary: June 6, 2016**

**Summary Tuesday May 31 – Friday June 3:** Inspection was suspended for Monday due to the Memorial Day holiday. No sheen or oil was observed at any of the inspection sites during the week. There was more rain this week but containments and vaults were pumped out by Hepaco as needed. The dye tracer study at the Crystal Substation is scheduled for June 16<sup>th</sup>.

Below you will find our daily observations for inspections:

**Tuesday 8:15 pm May 31 (mid tide)** – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen at docks or edge of water. Roaches Run parking area showed no signs of oil or sheen. Hepaco pumped rain water out of electrical vaults inside the Station.

**Wednesday 8:45 am June 1 (low tide)** – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen at boat ramp or dock area. Roaches Run parking area showed no signs of oil or sheen.

**Thursday 8:15 am June 2 (low tide)** – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. The absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

**Friday 10:00 am June 3 (low tide)** – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. Vaults inside station were dry.

Jason P. Ericson, PG  
Dominion Resources Services, Inc.  
Environmental Policy  
5000 Dominion Blvd  
Glen Allen, VA 23060  
Phone: (804) 273-3012  
Mobile: (804) 317-9464  
Fax: (804) 273-2964

---

**CONFIDENTIALITY NOTICE:** This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.